			to put all promises in writing. Keep this form.	
Mazda CX-5		2021 YEAR	JM3KFBCM2M0351278 VEHICLE IDENTIFICATION NUMBER (VIN)	
			WARRANTY	
	R DOES NOT PROVIDE	A WARRANTY FOR AN	Y REPAIRS AFTER SALE.	
	LER WA	RRANI	ſ	
FULL WARRA	ANTY.			
that fail during explain warra	g the warranty period. As	sk the dealer for a copy of , and the dealer's repair	and <u>100</u> % of the parts for the covered systems of the warranty, and for any documents that obligations. <i>Implied warranties</i> under your	
SYSTEMS COVERED:		DURATIO	DURATION:	
ENGINE		1,000 mil	1,000 miles	
TRANSMISSION		1,000 mil	1,000 miles	
POWER STEERING		1,000 mil	1,000 miles	
AIR CONDITIONING		1,000 miles		
Wearable parts such as brake	es, tires, or alignments ARE NOT	Warrantied		
NON-DEALER W	ARRANTIES FOR	R THIS VEHICLE	:	
MANUFACTURER components of the		PPLIES. The manufactu	rer's original warranty has not expired on some	
MANUFACTURER	'S USED VEHICLE WAR	RANTY APPLIES.		
OTHER USED VEH	HICLE WARRANTY APP	LIES.		
Ask the dealer for a copoligations.	py of the warranty docum	nent and an explanation of	of warranty coverage, exclusions, and repair	
coverage, deductib		. If you buy a service co	le for an extra charge. Ask for details about ntract within 90 days of your purchase of this ditional rights.	
	E YOUR MECHANIC C	AN INSPECT THE VEL	ICLE ON OR OFF THE LOT.	
-		-		
how to obtain a vehicl	le history report, visit ftc	.gov/usedcars. To chec	<b>SAFETY RECALLS.</b> For information on ck for open safety recalls, visit safercar.gov. The make the best use of the resources on	

Here is a list of some major defects that may occur in used vehicles.

#### Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame **Engine** 

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

## Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

# Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

#### Cooling System

Leakage including radiator Improperly functioning water pump

#### Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

### Fuel System

Visible leakage

#### Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

## Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags** 

#### Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

# Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning

#### Tires

Tread depth less than 2/32 inch Sizes mismatched

### Visible damage

improperly

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

### Exhaust System

Leakage Catalytic Converter

DEALER NAME	
AutoUSA, Ltd.	
ADDRESS 1316 E. Irving Blvd, Irving, TX	75060
TELEPHONE	EMAIL
972-438-9191	info@autousatexas.com
FOR COMPLAINTS AFTER SALE, CONTACT:	070 400 0404
Contact service department at	972-438-9191

**IMPORTANT:** The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).